

Phone: +385 1 6259 373
+385 1 6259 589
+385 1 6259 372
+385 1 6259 381
Fax: +385 1 6259 374
AFS: LDZAYOYX
Email: aip@crocontrol.hr
URL: <https://www.crocontrol.hr>



AIP SUP 003/2024
Effective Date: 04-Apr-2024
End Date: UFN
Publication Date: 04-Apr-2024

LDZA - ZAGREB/Franjo Tudjman Airport - Reconstruction works on the TWYs F, D and E

1. INTRODUCTION

At ZAGREB/Franjo Tudjman Airport, reconstruction works will be carried out on TWYs F, D and E (with an impact on TWYs G and H).

Works are planned to be performed from **2nd of May - 31st of August 2024**.

Works include the presence of men and equipment, and the works coordinator will be in contact with TWR.

This AIP SUP contains information on temporary changes and procedures that will be applied during works, and, if not published here, all related information will be subsequently promulgated via NOTAM.

2. LOCATION OF WORK ZONES AND THEIR ACTIVATION

Locations of work zones, through phases of execution, are shown in Appendix 1 (Index chart with graphical representation of the work phases).

The activation time of the each individual phase of works will be promulgated via NOTAM.

3. OPERATIONAL IMPACTS

During the works, due to capacity reduction, the operations of certain types of flights will not be approved (VFR, TECR FLT, ALTN, Training FLT, etc.).

For aircraft take-off and landing operations, depending on the RWY in use and the phase of works, possible RWY back-track should be taken into account (can be expected).

See AIP LDZA AD 2.9/4 - RWY 22 Turn pad restriction (180° turn on Turn Pad for aircraft with wheel base more than 25.6 M is not possible) and LDZA AD 2.24.1 ADC - 1 - THR 22 Runway Turn Pad marking RESTRICTION - graphical representation.

Due to these operations, RWY 04/22 occupancy time will be increased.

PPR is mandatory for all non-scheduled flights.

During works, mandatory taxi instructions will be provided via ATC.

Low Visibility Procedures (LVP) will be suspended.

All changes will be subsequently promulgated by NOTAM.

4. ENQUIRIES

Enquiries related to operational changes:
Airport Duty Manager - H24


Email: koordinatori@zag.aero

Phone: +385 1 4562 113

*This AIP SUP cancels and replaces AIP SUP 002/2024.
Record entry of AIP SUP 003/2024 in GEN 0.3.
Delete entry of AIP SUP 002/2024 in GEN 0.3.*

Ref AIP: LDZA AD 2

AERODROME CHART - WORKING ZONE LOCATION



OVA STRANICA JE NAMJERNO OSTAVLJENA PRAZNA
THIS PAGE INTENTIONALLY LEFT BLANK